




NRAY SERVICES INC.

56A Head Street Dundas Ontario, Canada L9H 3H7

Phone: 905.627.1302 Fax: 905.627.5022

Email: info@nray.ca URL: www.nray.ca

NRAY Neutron Radiography Sample Image - O-Ring Placement



The image above is a neutron radiograph of a fuel injector base component. The o-ring between the injector and the base is identified in the image by a circle. It is clearly seen that the o-ring in question is misaligned. Neutron radiography is a very useful and effective technique for identifying missing or misplaced o-rings.